

**INFORME MONITOREO**

<b>Preparado para:</b>	
<b>Preparado por:</b>	
<b>Lugar:</b>	TALADRO CCDC-036 / Tambococha D
<b>Fecha de monitoreo:</b>	24 Enero del 2018
<b>Tipo de monitoreo:</b>	Mapa de Isófonas

**RESULTADOS**

<b>PUNTO DE MEDICIÓN</b>	<b>COORDENADAS DE UBICACIÓN</b>		<b>VALOR OBTENIDO</b>
1	434.742	9'903.681	108
2	434.734	9'903.688	100
3	434.745	9'903.692	103
4	434.748	9'903.682	101
5	434.749	9'903.682	93
6	434.743	9'903.682	91
7	434.735	9'903.682	87
8	434.729	9'903.682	92
9	434.732	9'903.682	89
10	434.744	9'903.682	90
11	434.754	9'903.682	85
12	434.757	9'903.682	76
13	434.747	9'903.682	83
14	434.736	9'903.682	80
15	434.729	9'903.682	76
16	434.797	9'903.682	67
17	434.760	9'903.682	67
18	434.715	9'903.682	68
19	434.659	9'903.624	62
20	434.655	9'903.656	60
21	434.673	9'903.662	60
22	434.706	9'903.658	69
23	434.692	9'903.676	72
24	434.719	9'903.695	80
25	434.732	9'903.699	82

<b>PUNTO DE MEDICIÓN</b>	<b>COORDENADAS DE UBICACIÓN</b>		<b>VALOR OBTENIDO</b>
26	434.753	9'903.706	72
27	434.766	9'903.683	75
28	434.786	9'903.693	65
29	434.781	9'903.726	65
30	434.748	9'903.730	71
31	434.724	9'903.734	74
32	434.692	9'903.735	68
33	434.644	9'903.723	62
34	434.664	9'903.708	61
35	434.633	9'903.754	59
36	434.677	9'903.769	64
37	434.708	9'903.761	71
38	434.730	9'903.770	77
39	434.765	9'903.767	69
40	434.767	9'903.780	72
41	434.760	9'903.779	107
42	434.754	9'903.778	93
43	434.758	9'903.786	79
44	434.762	9'903.774	79
45	434.757	9'903.793	67
46	434.741	9'903.779	84
47	434.735	9'903.791	80
48	434.691	9'903.797	75
49	434.631	9'903.783	60
50	434.624	9'903.807	60
51	434.622	9'903.825	61
52	434.637	9'903.807	62
53	434.679	9'903.803	74
54	434.684	9'903.828	64
55	434.696	9'903.834	61
56	434.710	9'903.808	73
57	434.737	9'903.812	74
58	434.759	9'903.828	63
59	434.751	9'903.843	62
60	434.728	9'903.843	60

**Acreditación:** Certificado N° OAE LE 2C 07-001 Laboratorio de ensayos / [www.abrus.com.ec](http://www.abrus.com.ec)

Anexo 1. Mapa de Ubicación de puntos de Monitoreo.

Anexo 2. Mapa de Isófonas.